

## WILDFIRE SAFETY IMPROVEMENTS PROGRESS CALAVERAS COUNTY



## Below is an overview of our progress on key wildfire safety improvement work as of March 31, 2021.

	COMPLETE THROUGH 20201		2021 TARGET		2021 COMPLETE	
Community Resource Center (CRC) Sites Ready	<b>5</b> Indoor	<b>6</b> Outdoor	N/A	<b>\_</b> 2	5 Indoor	<b>6</b> Outdoor
Community-Based Organization (CBO) Partnerships in Place	<b>8</b> Partnerships		<b>1</b> Partner	rship	<b>1</b> Partnership	
System Hardening Complete	<b>2</b> Line Miles		1 Line M	∕lile	<b>O</b> Line Miles	
Transmission and Distribution Sectionalizing Devices Installed	19 Devices		2 Device		<b>O</b> Devices	
<b>Enhanced Vegetation Management</b> Complete	_	<b>91</b> Miles	<b>O</b> Line Miles		<b>O</b> Line Miles	
Weather Stations Installed	_	<b>19</b> tions	N/A <sup>3</sup>		<b>1</b> Station	
High Definition Cameras Installed	Cam	4 neras	N/A <sup>3</sup>		<b>O</b> Cameras	


<sup>1</sup> Cumulative progress from 2018 through 2020

**Note:** Additional wildfire safety work is planned for this year and will be available in the next progress update. All work plans are subject to change due to weather, access or other schedule constraints.



## PG&E is prioritizing its wildfire safety work by:

- Locations with the highest risk of wildfire
- Locations that will make our system safer and improve PSPS events





<sup>2</sup> CRC planning for 2021 is conducted in coordination with local agencies/tribes and is ongoing

<sup>3</sup> Locations identified on a monthly basis